
FIG.1



2/22

FIG.2A







FIG.2B





5/22

FIG.4A







FIG.4B

7/22

FIG.5A







FIG.5B



10/22




FIG.8




FIG.9





FIG.10A



14/22

FIG.10B






FIG.10C








FIG.13




FIG.14




FIG.15




FIG.16




FIG.17




FIG. 18

22/22									
REPORTING METHOD	LED DISPLAY ETC.	LED DISPLAY ETC.	LED DISPLAY ETC.	LED DISPLAY ETC.	LCD, LED DISPLAY ETC.	LCD, LED DISPLAY ETC.	LCD, LED DISPLAY ETC.	LCD, LED DISPLAY ETC.	
REPORTS TO USERS	FAILURE OF DISPLAY OPERATIONS BLOCK IS INDICATED BY BASE BLOCK	FAILURES OF DISPLAY OPERATIONS BLOCK AND 2ND OPERATIONS BLOCK ARE INDICATED BY BASE BLOCK	FAILURES OF DISPLAY OPERATIONS BLOCK AND 1ST OPERATIONS BLOCK ARE INDICATED BY BASE BLOCK	FAILURES OF DISPLAY OPERATIONS BLOCK AND 1ST AND 2ND OPERATIONS BLOCKS ARE INDICATED BY BASE BLOCK		FAILURE OF 2ND OPERATIONS BLOCK IS INDICATED BY DISPLAY OPERATIONS BLOCK AND BASE BLOCK	FAILURE OF 1ST OPERATIONS BLOCK IS INDICATED BY DISPLAY OPERATIONS BLOCK AND BASE BLOCK	FAILURES OF 1ST AND 2ND OPERATIONS BLOCKS ARE INDICATED BY DISPLAY OPERATIONS BLOCK AND BASE BLOCK	
OPERATIONS	BASIC OPERATIONS ARE AVAILABLE	NO OPERATIONS ARE AVAILABLE	ONLY SIMPLE COPY OPERATION IS AVAILABLE	NO OPERATIONS ARE AVAILABLE	NORMAL OPERATIONS	FUNCTIONS OF 2ND OPERATIONS BLOCK ARE INCORPORATED INTO DISPLAY OPERATIONS BLOCK	FUNCTIONS OF 1ST OPERATIONS BLOCK ARE INCORPORATED INTO DISPLAY OPERATIONS BLOCK	FUNCTIONS OF 1ST AND 2ND OPERATIONS BLOCKS ARE INCORPORATED INTO DISPLAY OPERATIONS BLOCK	
3RD OPERATIONS BLOCK	0	×	0	×	0	×	0	×	
1ST 2ND 3RD OPERATIONS OPERATIONS BLOCK BLOCK	×	×	×	×	0	0	0	0	
1ST OPERATIONS BLOCK	0	0	×	×	0	0	×	×	